INOVATE Getting Started Guide

Table of Contents

Chapter 1 About INOVATE

With INOVATE, Everyone Innovates Faster 1-3
INOVATE – Innovative 3D Communication for the Desktop 1-3
Parts 1-3
Assemblies and Products 1-5
Working with INOVATE 1-5
Setting the Scene 1-5
The Stages of an INOVATE Project 1-6
Visual and Precision Part Design 1-6
INOVATE Features 1-7

Chapter 2 Starting INOVATE

System Requirements 2-3
What You Need to Know to Work with INOVATE 2-3
Installation 2-3
Installing INOVATE under Windows 2000, Windows 98, and Windows NT 2-3
Starting INOVATE 2-4
Navigating the System 2-5
The INOVATE Window 2-5
Menus 2-5
Toolbars 2-6
Catalogs 2-7
Saving Your Work 2-7
Exiting INOVATE 2-8
Getting Help and Other Information 2-8
Tooltips 2-8
The Help Tool 2-8
INOVATE Technical Support 2-9
INOVATE Web Site 2-9

Chapter 3 INOVATE Quick Start

Setting Up the Working Environment 3-3
Using IntelliShapes, SmartDimensions and SmartSnap 3-3
Creating a New IntelliShape Feature by Sketching a Profile 3-5
Using Direct Face Modeling™ 3-7
Shelling a Part 3-8
Blending Edges 3-9
Using a Custom Hole 3-10
Creating and Using Custom Catalogs 3-11
Importing a Part 3-11
Using the Mate and Align Positioning Tool 3-11
Creating an Assembly 3-12
Continuing the Process 3-13

Chapter 4 3D Design Overview

Knowing the Process 4-3
Starting the Project 4-3
Building a Part 4-3
Assembling Parts 4-6

Rendering a Part 4-7
Animating a Part 4-7
Communicating a Part 4-7

Chapter 5 Creating and Editing Shapes Using 2D Cross-sections

Creating the Flywheel with a Spin IntelliShape 5-3
Setting the Drawing Options 5-3
Drawing the Spin Profile 5-5
Positioning Lines Using Endpoint Position Dimensions 5-5
Accurately Positioning Lines Using Curve Dimensions 5-7
Relocating the Coordinate Axes of Endpoint Dimensions 5-8
Positioning Multiple Lines Simultaneously 5-9
Using Shape Handles 5-10
Editing the Cross-section of an Existing IntelliShape 5-11
Using the Offset Command 5-12
Using 2D Constraints 5-13
How Constraints Affect the Behavior of Shape Handles 5-17
Drag-and-Drop Modeling vs. 2D Cross-section Modeling 5-19
Setting Part and IntelliShape Names and Color 5-20
Creating a Bolt Hole Pattern 5-21
Creating the Crankshaft 5-22
Adding More Shapes to the Crank Shaft 5-24
Creating the Crank Arm 5-25
Creating Tangent Lines 5-26
Creating Tangency and Concentric Constraints 5-27
Parametric Constraints with Expressions 5-29
Creating an Assembly 5-30
Adding Gear Teeth to the Flywheel 5-31
Creating Linked Instances of a Cross-section 5-33
2D Fillets vs. 3D Blends 5-34

Chapter 6 Inside the TriBall

Anatomy of the TriBall 6-3

Chapter 7 Rendering With INOVATE

Rendering Levels 7-3
Lighting 7-7
Perspective 7-9
Surface Smoothness 7-10
Printing Images 7-11
Rendering Time 7-11
Exporting Images 7-13
Reflectivity: Ray Tracing and Reflection Mapping 7-13
Transparency Effects 7-15
Draw Edges, Emission, and Technical Publications 7-18
Advanced Shadow Settings 7-19
Templates 7-21
The Projection Tools 7-23
Slide Projector 7-23
Cylindrical 7-23
Spherical 7-24
Bump Maps 7-24
Adding a Custom SmartPaint Surface to a Catalog 7-27

Chapter 8 Animating with INOVATE

Anchor-Animation Relationships 8-3
Creating an Exploded Parts Animation 8-5
Adjusting Timing with the SmartMotion Editor 8-6
Modifying a SmartMotion 8-7
Creating Animations for General Viewing 8-9
Creating a Dynamic Cutaway Animation 8-10
Exporting Animations 8-13
Animation Compression and Color Depth 8-13
AVI 8-13
Animated GIF 8-13

Chapter 9 Special Function Key Assignment

File/Edit Function Keys 9-3
Camera Function Keys/Buttons 9-3
TriBall Function Keys 9-3
Positioning Function Keys 9-4
Rendering Function Keys 9-4
3D SmartDimensions Function Keys 9-4
Cross-section Creation Function Keys 9-4
Handle (sizebox, face, profile, sheet metal, etc.) Function Keys 9-4
Miscellaneous Function Keys 9-5